7 7 7 7 mm	Oranienbur	g Airfield	25
channe and have been	ennen i Green hande de de de la companya de la companya de la companya de la companya de la decima de la compa		25X
/ALUAT	TION_		25X1
ITE OI	F CONTENT_		25X
			manda manda a di mandra a signat un signat del se distributi del manda del m
			RED 24 March 1953
GES_			
			on ditto
MAKK		er kindres dan nama, dan nyakar harini sara dandan da 1920-146, ada-ada-ada-arab 172 37, B. US. Sakabangar nyaran 1934 (1866 salab	and the substantial section of the s
BB/M - Hart Date Tris Ad.	k er det sters (skisk i redferder - er entriplek (restille hellsteller skiet i deburger ensem	This is UNEVALUATED Info	ormation
h-ha dintrasanga	enter en activis, mercanistation de autoritation de la companya de la companya de la companya de la companya d La companya de la co	TIIIS IS ONLYALOATED IIII	ormation 25X
-			20/
	stones and san runway were al the old hangar intersection w	d were removed along the entire : so removed. Some of the poles wer in the northern section of the : 1th the sour track. Lewes were f.	under way on the southern section of instruction material, boards, crushed runway. The light poles along the re-erected along the taxiway to field and along the taxiway near the itted on these poles. A concrete
2.	stones and san runway were all the old hangar intersection washing machine construction sthe field. In February, sketch of the road leading a	d were removed along the entire : so removed. Some of the poles wer in the northern section of the : ith the spur track. Lamps were f: was still observed at the southehed. No work was being done on the the location and airfield. A strip at a right angling wilhelminement to Velterer I	runway. The light poles along the runway. The light poles along the re-erected along the taxiway to field end along the taxiway near the itted on these poles. A concrete ern section of the runway, next to a he fence along the western border of 25. 25. d direction of the runway and a le to the runway, 290 meters from the Bridge was being excavated. Up to exiways, but the area was surveyed sever
	stones and san runway were al the old hangar intersection w mixing machine construction s the field. In February, sketch of the road leading a 25 February, n times. The damage cau	d were removed along the entire : so removed. Some of the poles wer in the northern section of the : ith the spur track. Lamps were f: was still observed at the south hed. No work was being done on the the location and airfield. A strip at a right angl long Wilhelminenhof to Veltener for changes were observed on the tag sed by the explosion of a mine of	runway. The light poles along the runway. The light poles along the re-erected along the taxiway to field and along the taxiway near the itted on these poles. A concrete sern section of the runway, next to a he fence along the western border of 25. d direction of the runway and a le to the runway, 290 meters from the Bridge was being excavated. Up to exiways, but the area was surveyed severage the runway was not remained and the runway and a second the runway and the runway
	stones and san runway were al the old hangar intersection w mixing machine construction s the field. In February, sketch of the road leading a 25 February, n times. The damage cau 25 February. Se In February, 1	orantenoury attricted. All the cold were removed along the entire is so removed. Some of the poles were in the northern section of the ith the spur track. Lamps were fix was still observed at the souther hed. No work was being done on the telegraph of the location and airfield. A strip at a right angle long Wilhelminenhof to Veltener her changes were observed on the telegraph of the explosion of a mine aloldiers were searching for other args quantities of cement. Crushe	runway. The light poles along the re-erected along the textway to field and along the taxiway near the itted on these poles. A concrete ern section of the runway, next to a he fence along the western border of 25. d direction of the runway and a le to the runway, 290 meters from the Bridge was being excavated. Up to exiways, but the area was surveyed seviced the runway was not repaired on buried mines.
3.	stones and san runway were al the old hangar intersection w mixing machine construction s the field. In February, sketch of the road leading a 25 February, n times. The damage cau 25 February. S In February, l arrivel of nume The search for of the Bauunion to Schorfheide start on the te	d were removed along the entire : so removed. Some of the poles were in the northern section of the : ith the spur track. Lamps were f: was still observed at the souther the location and sirfield. A strip at a right angle long Wilhelminenhof to Veltener is changes were observed on the test of the second second second second the second	runway. The light poles along the re-erected along the textway to field and along the taxiway near the itted on these poles. A concrete ern section of the runway, next to a he fence along the western border of 25. d direction of the runway and a le to the runway, 290 meters from the Bridge was being excavated. Up to exiways, but the area was surveyed seviced the runway was not repaired on buried mines.
30	stones and san runway were al the old hangar intersection was mixing machine construction state field. In February, sketch of the road leading a 25 February, n times. The damage cau 25 February. Surrivel of number in the Bauunion to Schorfheide start on the tais to be provided.	d were removed along the entire : so removed. Some of the poles wer in the northern section of the : ith the spur track. Lamps were f: was still observed at the southe hed. No work was being done on the the location and airfield. A strip at a right angl long Wilhelminenhof to Veltener for changes were observed on the te sed by the explosion of a mine al pldiers were searching for other arge quantities of cement, crushes erous concrete slabs was observed demolition blocks at the field on had left for other airfield con Concreting was scheduled to be existed with a glass roof, and barrace Work on the runway at Orenienbu	runway. The light poles along the re-erected along the textway to field and along the textway near the litted on these poles. A concrete ern section of the runway, next to a he fence along the western border of 25. d direction of the runway and a le to the runway, 290 meters from the Bridge was being excavated. Up to exiways, but the area was surveyed seventiated mines. 25. Long the runway was not repaired on buried mines. ed stones and gravel arrived. The lin the last days of February. I continued until 2 March. Some workers astruction sites. Most of them had gone resumed in March. Work was also to buy to the north. Allegedly, the hanger
3. 4.0 5.0	stones and san runway were al the old hangar intersection was mixing machine construction at the field. In February, sketch of the road leading a 25 February, n times. The damage cau 25 February, So In February, I arrival of number the Bauuniot to Schorfheide start on the tris to be provided at the field blocks.	d were removed along the entire : so removed. Some of the poles wer in the northern section of the : ith the spur track. Lamps were f: was still observed at the southe hed. No work was being done on the the location and airfield. A strip at a right angl long Wilhelminenhof to Veltener for changes were observed on the te sed by the explosion of a mine al pldiers were searching for other arge quantities of cement, crushes erous concrete slabs was observed demolition blocks at the field on had left for other airfield con Concreting was scheduled to be existed with a glass roof, and barrace Work on the runway at Orenienbu	runway. The light poles along the runway. The light poles along the re-erected along the taxiway near the field and along the taxiway near the itted on these poles. A concrete ern section of the runway, next to a he fence along the western border of 25. 25. 25. d direction of the runway and a le to the runway, 290 meters from the Bridge was being excavated. Up to exiways, but the area was surveyed sevent according to the runway was not repaired on buried mines. ed stones and gravel arrived. The lin the last days of February. I continued until 2 March. Some workers estruction sites. Most of them had gone resumed in March. Work was also to be the north. Allegedly, the hangar eks buildings are to be constructed. Improvement auch to be searched for demolition 25x
3. 4.0 5.0	stones and san runway were al the old hangar intersection was mixing machine construction at the field. In February, sketch of the road leading a 25 February, n times. The damage cau 25 February, So In February, I arrival of number the Bauuniot to Schorfheide start on the tris to be provided at the field blocks.	orantenous attricted. All the cold were removed along the entire is so removed. Some of the poles were in the northern section of the ith the spur track. Lamps were fix was still observed at the souther hed. No work was being done on the telection and airfield. A strip at a right angling Wilhelminenhof to Veltener is changes were observed on the telection of a mine alloldiers were searching for other arge quantities of cement, crushed argument of the construction blocks at the field on had left for other airfield confidence which meet with the runwalled with a glass roof, and barraction was delayed until the area control of the confidence with the runwalled was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the area control of the confidence was delayed until the control of the confidence of the confidence of the confidence of the control of the confidence of the confidence of the control of the control of the confidence of the control of th	runway. The light poles along the runway. The light poles along the re-erected along the taxiway near the field and along the taxiway near the itted on these poles. A concrete ern section of the runway, next to a he fence along the western border of 25. 25. d direction of the runway and a le to the runway, 290 meters from the Bridge was being excavated. Up to exiways, but the area was surveyed seviced the runway was not repaired on buried mines. ed stones and gravel arrived. The in the last days of February. I continued until 2 March. Some workers estruction sites. Most of them had gone resumed in March. Work was also to be to the north. Allegedly, the hangar eks buildings are to be constructed. Improvement airfield was completed.

25 YEAR RE-REVIEW

Approved For Release 2009/02/18 : CIA-RDP80-00810A001000210009-8

25X1

SECRET/CONTROL - U.S. OFFICIALS ONLY

- 2 ···

Comment. In late December 1952, it was stated that the runway and taxiways were to be completed by 5 April 1953. Probably, this target date will not be kept. It was previously reported that above—ground construction was intended. This information requires confirmation.


25X1

SECRET/CONTROL - U.S. OFFICIALS ONLY

Annex

Oranienburg Airfield

25X1



SECRET/CONTROL - U.S. OFFICIALS ONLY SECURITY INFORMATION